

New Box #130**(From Original Box #64)**

1. Medsystem printouts 1995-96 of models run for the dipper crusher, pit reserves, geologic reserves, anchor hill pit reserves (610), etc.
2. anchor hill topo map
3. leach pad alternatives cost summary
4. 1996 Pit and Model updates
5. Blattner Invoices for work performed in 1997 (copied)
6. Blattner-Brohm Open Pit Agreement
7. Letters from Blattner to Brohm dated 1994 through 1997 (copied)
8. Blattner - Waste Materials Management, Spill Prevention, and Fuel Storage Plan for Site Construction and Contract Mining at Brohm/Anchor Hill
9. 1996 Anchor Hill Model and Pit Update
10. Blattner accident reports at Anchor Hill (copied)
11. Marvin Truhe's comments regarding the Open Pit Agreement
12. 1993 Brohm-Blattner agreement (copied)
13. LAC Minerals - Richmond Hill Mine Reclamation Contract 1994
14. Various Blattner correspondence (copied)

New Box #131 58 1094618**(From Original Box #60)**

1. Anchor Hill Monitoring - 1997 - Excess ARD Waters Contingency Plan
2. Mid-Continent
3. Empty folders
4. Reverse Osmosis - letter from SDDENR 1994 to Brohm
5. Notice of Violation - letter from SDDENR 1997 to Brohm
6. Permit Amendment - Mining and Minerals - regarding mine permits No. 439 and No. 462. Letter from SDDENR to Brohm 1995 (Notice of Decision)
7. Langley Conditions - letter from SDDENR to Brohm 1997
8. Hydrologic Monitoring Reports - 1999
9. Hydrologic Monitoring Reports - 1998
10. Hydrologic Monitoring Plan - letter from Brohm to SDDENR regarding the technical revision requirements
11. Leak Response Action Plan - Leakage Response Action Plan (LRAP) August 1996 by Brohm
12. LRAP Reports 1999
13. Maps - water level elevation in the bedrock and alluvial aquifers - fall 1994; water level elevation in the bedrock and alluvial aquifers - fall 1993; water level elevation in the bedrock and alluvial aquifers - summer 1996
14. Letter from SDDENR regarding the groundwater discharge plan application 3/3/1999
15. Groundwater well logs (copied)
16. 1998 Annual - hydrologic monitoring report
17. Permit GWD #3-88 - correspondence between Brohm and SDDENR 1995-1999
18. Permit Reporting 1999 - GWD #3-88
19. Spill Info GWD #3-88

20. CN / Arsenic loading GWD #3-88
21. Site Info - drawings and monitoring well locations
22. Anchor Post Closure Seepage report prepared by SRK for Brohm in 1996
23. ARD Drift Monitoring -1997 correspondence between Brohm and SDGFP
24. CUP #206 – list of requirements
25. Sampling Info – list of reference methods and parameters for sampling inorganic and organic water samples
26. Aquatic Monitoring Plan – submitted by Brohm to SDDENR in August 1997
27. empty folders
28. Spill Contingency Plan – prepared by Brohm for the Anchor Hill Project 1997
29. H2O Standards – guidelines and literature regarding water and discharge standards by the State of South Dakota
30. Cockrell – Christensen, Moore & Cockrell PC letters to Brohm regarding discharge monitoring results for the SWDP and the NPDES permits 1998-1999
31. Storm Water Pollution Prevention Plan 1996 for Brohm
32. Best Management Plan 1996 for Brohm
33. Purchases 1998 – Brohm purchase requisition forms
34. Budget – information regarding the 1998 environmental budget
35. Labels for SDDENR and blank labels
36. P.L. – empty
37. Forms Master – blank Mid-Continent lab forms
38. Forms Copy – surface water sampling, personnel action, and other forms (blank)
39. Purchases 1999 – Brohm purchase forms
40. Purchase orders – empty
41. Brohm phone list
42. mouse pad
43. Autocad – cheat sheet
44. SWDP Samples – SWDP #SD-0026891 & Monthly Samples – Mid-Continent lab results
45. Permit – correspondence between Brohm and SDDENR regarding the surface water discharge permit (SWDP) 1998
46. Chadwick & Associates letter/report to Brohm on bioassays 1999
47. Study 19 – 1999 SWDP – Environmental Resources Associates water analysis and submittal of information to EPA
48. small note pad with a few notes on water samples
49. calculators
50. picture of hunter with buck
51. blank note pad and computer paper and envelops
52. Contractors planning manual
53. Encore CX 816 – 3672